

**Federal Communications Commission**

---

**Before the  
Federal Communications Commission  
Washington, D.C. 20554**

In the Matter of	)	
	)	
Capstar Radio Operating Company	)	File No. EB-11-PA-0196
Registrant of Antenna Structures	)	File No. EB-11-PA-0197
ASR # 1031109, 1031110, 1031111	)	File No. EB-11-PA-0198
Whitehall, Pennsylvania	)	
	)	NOV No. V201232400001

**NOTICE OF VIOLATION**

**Released: October 7, 2011**

By the District Director, Philadelphia Office, Northeast Region, Enforcement Bureau:

1. This is a Notice of Violation ("Notice") issued pursuant to section 1.89 of the Commission's rules<sup>1</sup> to Capstar Radio Operating Company, owner of antenna structures 1031109, 1031110, and 1031111 located in Whitehall, Pennsylvania.
2. On September 14, 2011, an agent of the Commission's Philadelphia Office inspected antenna structures 1031109, 1031110, and 1031111, which are located at the coordinates 40° 39' 37.0" North Latitude 075° 30' 49.0" West Longitude; 40° 39' 38" North Latitude 075° 30' 52.0" West Longitude; and 40° 39' 39.9" North Latitude 075° 30' 55.2" West Longitude, respectively, and observed the following violation:

47 C.F.R. § 17.4(g): "The Antenna Structure Registration Number must be displayed in a conspicuous place so that it is readily visible near the base of the antenna structure. Materials used to display the Antenna Structure Registration Number must be weather-resistant and of sufficient size to be easily seen at the base of the antenna structure." At the time of inspection, no Antenna Structure Registration Numbers were visible at the base of antenna structures 1031110 and 1031111. The agent also observed that the sign displaying the Antenna Structure Registration Number for antenna structure 1031109 was not properly labeled.<sup>2</sup>

---

<sup>1</sup> 47 C.F.R. § 1.89.

<sup>2</sup> The sign displaying the antenna structure registration number for the antenna structure 1031109 was missing the leading "1" in the number.

**Federal Communications Commission**

---

3. Pursuant to section 403 of the Communications Act of 1934, as amended,<sup>3</sup> and section 1.89 of the Commission's Rules, Capstar Radio Operating Company must submit a written statement concerning this matter within 20 days of release of this Notice. The response must fully explain the violation, must contain a statement of the specific action(s) taken to correct the violation and preclude recurrence, and should include a time line for completion of pending corrective action(s). The response must be complete in itself and signed by a principal or officer of Capstar Radio Operating Company. All replies and documentation sent in response to this Notice should be marked with the File No. and NOV No. specified above, and mailed to the following address:

Federal Communications Commission  
Philadelphia Office  
One Oxford Valley Building, Suite 404  
2300 East Lincoln Highway  
Langhorne, Pennsylvania 19047

4. This Notice shall be sent to by Certified Mail/Return Receipt Requested and regular mail to Capstar Radio Operating Company at its address of record.
5. The Privacy Act of 1974<sup>4</sup> requires that we advise you that the Commission will use all relevant material information before it, including any information disclosed in your reply, to determine what, if any, enforcement action is required to ensure compliance. Any false statement made knowingly and willfully in reply to this Notice is punishable by fine or imprisonment under Title 18 of the U.S. Code.<sup>5</sup>

FEDERAL COMMUNICATIONS COMMISSION

Gene J Stanbro  
District Director  
Philadelphia Office  
Northeast Region  
Enforcement Bureau

---

<sup>3</sup> 47 U.S.C. § 403.

<sup>4</sup> P.L. 93-579, 5 U.S.C. § 552a(e)(3).

<sup>5</sup> 18 U.S.C. § 1001 *et seq.*